



POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION

SITE NUMBER

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME

COE Mfg Co

B. STREET (or other identifier)

609 Bank St

C. CITY

Painesville

D. STATE

Ohio

E. ZIP CODE

F. COUNTY NAME

Lake

G. OWNER/OPERATOR (if known)

1. NAME

2. TELEPHONE NUMBER

H. TYPE OF OWNERSHIP (if known)

☐ 1. FEDERAL☐ 2. STATE☐ 3. COUNTY☐ 4. MUNICIPAL☒ 5. PRIVATE☐ 6. UNKNOWN

I. SITE DESCRIPTION

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.)

DEPA

K. DATE IDENTIFIED

(mo., day, & yr.)
10/9/80

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

M. PREPARER INFORMATION

1. NAME

J. Fager

2. TELEPHONE NUMBER

886-6714

3. DATE (mo., day, & yr.)

11/12/80



REPORT #: 789

DATE: 9/30/80

HAZARDOUS WASTE HOTLINE REPORT FORM

TAKEN BY: CLASON

SITE NAME: Coe Manufacturing Company

ADDRESS: 609 Bank Street; Painesville, OH

COUNTY: Lake County

SITE DESCRIPTION:

Caller reports company has been dumping materials (oftentimes solid waste debris, but has also seen some 55-gallon drums) off ravine in back of the company's property and into the Grand River.

NAME OF CALLER: Colleen Marshall

ADDRESS: 458 Valley View Drive

Painesville, OH 44077

PHONE: 216/352-2051

Reported to other agencies?

Follow-up Information Requested? YES, PLEASE

Immediate Action Taken: